



METRIC

TAPE SEGMENT
FOR
GEAR GRINDER



NOTE:
All pencil lines except construction and projection lines are dark lines. Copy the given views starting at A. Omit all inclined lettering. Make your dark lines as black as those above.

GRADE	2	3	4	5	ALPHABET OF LINES Draw Given Views
	6	7	8	9	

DRAWING
1-3